# MARYLAND INVENTORY OF

# Maryland Historical Trust HISTORIC PROPERTIES State Historic Sites Inventory Form

Survey No. B-4330 Magi No. DOE \_yes \_no

	e (indicate pre	eferred name)		
	106 N. Howard S	treet		minued entires.
historic	Elegance			
and/or common	AND IN TERE	west ominibud it	1840 commercia	southweight
2. Loca	tion	i etroccures.	Liswydisg owd I	TOUGH Die Jeels
street & number	106 N. Howard	Street	Minesentory alti a domestic onti	not for publication
city, town	Baltimore	vicinity of	congressional district	Seventh
state	Maryland	county	Baltimore	enibleed Joses
3. Class	sification	led same based in	grat meansts a light bexed sign	arade. A plast
Category  district building(s) structure site object	Ownership public x private both Public Acquisition in process being considered X not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted X no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
name	er of Proper Market Center I	REPRESENTED FOR	nd mailing address	es of <u>all</u> owners)
street & number	8201 Symphony I	Orive	telephone	
city, town	Baltimore	state	and zip code	MD 21208
5. Loca		al Description		
		imore City Court	house	SEB8241
courthouse, regist	100 N. Calvert	Street, Room 61	0	liber 250
street & number				MD folio
city, town	Baltimore		state	MD
	acontation	in Evictina	Historical Sur	vove
	cociliation	III Existing	nistoricar bur	veys
6. Repr				
6. Repr			federal sta	ate county loc

### 7. Description

Survey No. B-4330

Condition
\_\_\_ excellent
\_\_\_ good

\_\_ deteriorated \_\_ ruins \_\_ unexposed Check one \_\_ unaltered \_\_ altered Check one
X\_ original site

\_\_moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Resource Count: 1

This circa 1840 commercial building faces east on N. Howard Street and abuts two partywall structures. The two-bay, threestory, brick building has 20th-century alterations on the first story and late 19th-century alterations on the second. It may have originally been a domestic building converted to commercial usage. The brick is painted cream and the trim is painted mustard yellow. The street frontage is 16' and the depth is 64'6".

The first story has been completely altered. Most of the vacant building is currently obscured by roll-down theft guards. A glass door with transom is positioned on the north edge of the facade. A plastic, boxed sign board runs between the first and second stories. The metal ribs for an awning hang without fabric.

The second story has a tripartite "Chicago" window centered on the facade. Set in wood surrounds, the window consists of a large central pane of glass flanked by narrow 1/1 sash on either side. Each window has a transom. The center transom has silver tape outlining a geometric border around the perimeter of the glass. A molded lintel runs across the tops of the windows. It has a fillet, quarter round, bead and back band profile.

The third story has two 2/2 sash windows with stone sills and brick splayed jack arches.

The cornice is of three corbelled brick courses.

The back (west) wall is three bays wide and two stories high. The first story has a window in the first bay, a door in the second, and a now-blocked door in the third. The second story has three now-blocked windows. The windows have wood sills and header brick lintels. The cornice is a one corbelled brick course.

1400 1500 1600 1700	istoric 1499 1599 1699 1799	ard ard ard ard ard ard ard ard X co	of Significance cheology-prehistoric riculture chitecture mmerce mmunications	oric _	com con eco edu eng exp indu	munity servation cation ineerin	y planning on s	g  ent	law litera milita musi philo	ture iry c sophy	rchitectur	E 1713	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates	irca	1840, late	er a	ulider/	Archi	tect	unk	now	n			<del>o maisil ku</del>
check:	and	d/or	e cui	_A	В	C	D	L.		U C			1 - 2
	Appli	cable	Exception:	A	B	c	D _	_E _	_F	G			
Direction of the second	Level	of S	ignificance:	n	ation	al _	_state	<u>X</u> 10	cal	- 1	بالمسلما		

Prepare both a summary paragraph of significance and a general statement of history and support. The architectural design of this three-story, two-bay building is a good example of a shop-house building dating to the second quarter of the nineteenth century, with late nineteenth-century commercial alterations. As originally constructed, the first story would have been used for commercial purposes and the upper stories would have been used as dwelling quarters. The later second-story tripartite window is indicative of the established commercial nature of the neighborhood by the end of the century, at which point the second-story of the shop-house was remodelled to boost commercial activity within the building.

The building's gable roof and brick splayed jack arches are typical of several circa 1830-1840 remodelled shop-houses found on the upper blocks of N. Howard Street. This example is the only one standing this far south on N. Howard Street, having escaped demolition by the conversion of the first and second stories to

## 9. Major Bibliographical References

Survey No. B-4330

Richard Longstreth, <u>The Buildings of Main Street: A Guide to American Commercial Architecture</u> (Washington, DC: Preservation Press, 1987).

Acreage of nominate	graphical Data ed property Baltimore East Qua			Quadr	angle scale
UTM References d	lo NOT complete UTM re	ferences			
Zone Easting	Northing	!	Zone	Easting	Northing
c L L L L L	44111111			Hili	Hillitate
E L L L L L		1	FLL		
GLJ LJ		į	н 🔲	بيا بلا	لتبابلتا
List all states and	I counties for properties o	verlapping st	ate or c	ounty boundar	ies
state	code	county	/		code
state	code	county	/		code
11. Form	Prepared By				
name/title	Diane Sha	W			
organization	C.H.A.P., Room	1037	d	Au	gust 12, 1991
	A17 E Favette	Street		(3	01) 396-4866

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

telephone

state

MD

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Baltimore

Maryland Historical Trust Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST DHCP/DHCL 100 COMMUNITY BLACE CROWNSVILLE, MD 21032-2023 301-514-7600



street & number

city or town

#### COMPREHENSIVE PLAN DATA

#### **HISTORIC CONTEXT:**

Geographic Organization: Piedmont

Chronological/Developmental Period:
Agricultural-Industrial Transition, 1815-1870

Industrial/Urban Dominance, alterations

Historic Period Themes: Architecture Economics

Resource Type: Building

Historic Environment: Urban

Historic Function and Use:

Residential/Commerical

Known Design Source: None

(596 W. LEXINGTON ST. ST. ST. 14 12 15/17 11 9/10 118 8 BRIDGE ¢ TUNNEL MARION ST. 28 B 29 30 1/2 31 3/7 N. HOWARD N, EUTAW 6 W. FAYETTE ST. (632)

CED BY P. WAINWRIGHT

REVISIONS LOTS 3 THRU TO CONSTO PER DEED (APP.,C.5H.9355 LOT 19/27 PER,PL.S.C.5H.85-133 LOTS 142 CONSTO PER DEED C. 3H.85-372

TERED BY P.W.

NOTICE

THIS IS A REAL PROPERTY PLAT AS PROVIDED FOR UNDER ARTICLE 76(d) OF THE CITY CHARTER IT IS COMPILED FROM TITLE AND OTHER SOURCES AND IS NOT AN AUTHENTIC SURVEY.

CITY OF BALTIMORE
DEPARTMENT OF PUBLIC WORKS


PROPERTY LOCATION DIVISION

WARD 4 SECTION 10 BLOCK 619

SCALE 1:50:0" DATE D

DATE DEC. 1966

B-4330 Elegance 106 N. Howard Street Block 0619, Lot 032 Baltimore City





B-4330 106 N. Howard St. Baltimore MD Brane Shaw 8/91 Manyland SHPO Facade, east elevation 1/2



B-4330 106 N. Howard St. (near) Baltimore MD Diane Shaw 8/91 Mary and 5HPD Rear alley (west elevation) 2/2